

R-1761

Exhibit 3 - Photograph [R-1761]



**SCREW THREAD MARKINGS
IN THERMOSTAT 5 O'CLOCK
APERTURE CONTINUING
INTO HOLE IN WALL**

Exhibit #3