

R-1767

Exhibit 9 - Photograph [R-1767]



MAGNET AGAINST  
MAGNET BACK-STOP

CLOSED CONTACTS

ADHESIVE BREAK & VIAL  
DISPLACEMENT CAUSED  
BY AND HELD BY HEAD OF  
THIRD SCREW

Exhibit #9

OVER-SIZED HEAD  
OF THIRD SCREW